

L1	A	124.0
L2	A	124.1
L3	A	124.2
L4	A	124.3
L5	A	124.4
START	E	124.0
X0	M	1.0
X1	M	1.1
X2	M	1.2
X3	M	1.3
X4	M	1.4
X5	M	1.5

SET
S "X0"
R "X1"
R "X2"
R "X3"
R "X4"
R "X5"

Segm.: 1
U "X0"
U "START"
R "X0"
S "X1"
Segm.: 2
U "X1"
U T 1
R "X1"
S "X2"
Segm.: 3
U "X2"
U T 2
R "X2"
S "X3"
Segm.: 4
U "X3"
U T 3
R "X3"
S "X4"
Segm.: 5
U "X4"
U T 4
R "X4"
S "X5"
Segm.: 6
U "X5"
U T 5
R "X5"
S "X0"
Segm.: 7
U "X1"
L S5T#1S
SE T 1
Segm.: 8
U "X2"
L S5T#1S
SE T 2

Segm.: 9
U "X3"
L S5T#1S
SE T 3
Segm.: 10
U "X4"
L S5T#1S
SE T 4
Segm.: 11
U "X5"
L S5T#1S
SE T 5
Segm.: 12
O "X1"
O "X2"
O "X3"
O "X4"
O "X5"
= "L1"
Segm.: 13
O "X2"
O "X3"
O "X4"
O "X5"
= "L2"
Segm.: 14
O "X3"
O "X4"
O "X5"
= "L3"
Segm.: 15
O "X4"
O "X5"
= "L4"
Segm.: 16
O "X5"
= "L5"